


CASE-STUDY: 2016 TOYOTA COROLLA S PLUS

Client Success Story – Car Parts USA



 **Car-Parts**usa
Right Parts, Guaranteed



Scan the QR Code

Client Overview

Client Name: Emily Carter


Location: Denver, Colorado

Vehicle: 2016 Toyota Corolla S plus: CVT Automatic Transmission

Mileage: 112,000 miles

Primary Use: Daily commuting and weekend road trips

Emily used her 2016 Toyota Corolla S plus every day for a 40-minute drive to work and weekend trips to the mountains. It had always been reliable but once it hit 100K miles, the transmission started acting up.





Challenges Faced By Emily

Emily began experiencing several persistent transmission problems,

- ◆ Jerky acceleration and hesitation when shifting from a stop
- ◆ Whining noise at highway speeds
- ◆ Check Engine Light with CVT-related error codes
- ◆ Slipping gears, especially during hill climbs

She took her car to a dealership where the diagnosis confirmed a failing CVT. The cost quoted for a brand-new OEM CVT unit with installation: \$5,800, well beyond her budget.

- ◆ **Dealership Estimate:** \$7,200, including engine and labor with no warranty at all.

The cost was well beyond Kevin's budget, and he was advised to consider selling or scrapping the vehicle.



Solution Provided By Car Parts USA

After looking into cheaper options, Emily got in touch with Car Parts USA. Our team helped her find a reliable replacement that didn't break the bank.

Our Engine Recommended Solution:

- ◆ Used OEM CVT transmission for 2016 Toyota Corolla S Plus.
- ◆ It has been fully checked, dyno-tested, and the mileage is confirmed.
- ◆ Includes torque converter and updated CVT fluid
- ◆ Backed by a up to 2 year parts warranty
- ◆ Parts warranty included

Total Project Cost:

- ◆ **Used OEM CVT Transmission:** \$1,950
- ◆ **Shipping:** Free
- ◆ **Installation by Certified Shop:** \$850


Total Project Cost \$2,800: Jordan saved over \$3,000 vs. dealership.

Implementation & Process

1. Old CVT unit removed carefully without damaging surrounding electrical harnesses and mounts.
2. The used CVT was installed, including a new transmission mount, filter, and Toyota CVT fluid.
3. Performed adaptive relearn procedure and updated transmission control software.
4. Car was test-driven for 30+ miles under various conditions to confirm smooth operation.
5. Total installation time: 2.5 business days



Installation Steps Included:



Smooth Acceleration

Fuel Economy

Error Coded

CVT Noise



Client Testimonial




Emily Carter
Denver, CO



I thought I'd have to trade in my car and go into debt for a new one. Car Parts USA gave me a reliable, affordable way to keep my Corolla running. It feels like new again!


Impact of the Solution


- ◆ Cost savings over \$3,000 saved as compared to dealer replacement
- ◆ Extended vehicle life at least 5+ more years of dependable use
- ◆ A reused transmission means fewer parts wasted and reduced environmental impact
- ◆ Emily can now drive confidently without fear of breakdowns



Conclusion

This case study shows how Car Parts USA helped a client overcome a major transmission failure in a cost-effective, environmentally friendly, and reliable way for their 2016 Toyota Corolla S plus. Emily got her car back on the road without breaking the bank by choosing a tested used OEM transmission.





Thank You!

For Choosing Our Products

www.car-partsusa.com

